

Vaisala HMW50U/Y humidity transmitter

Output quantities:	Relative humidity (%), temperature (°C/°F) in model HMW50Y		
Operating voltage:	Output	DC	AC
	0-1 V	12-35 V	12-24 V
	0-10 V	15-35 V	15-24 V
Two analog outputs:	0-1 V, 0-10 V		

Wiring diagram

